Work Order ID 50198

July 10, 2009 11:24:13 AM



Page 1

Item ID:

D2989-043

Accept

Setup Start



Revision ID:

D

Item Name:

Basket Lid Assembly

Start Date:

7/16/09

Start Oty: 1.00

Required Date: 7/28/09

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date: Date:

Tooling:

Date: Date: Run

Start

Stop

Stop



Sequence ID/ **Work Center ID**

Operation Description Set Up/ **Run Hours**

SPC (Y/N):

Draw Number Draw Plan Rev.

Accept Qty Code

Reject Oty

Reject Insp. Number Stamp

Draw Nbr

Revision Nbr

D2989

Rev D

100

Large Fab

Large Fab

Memo

0.00

0.00

Large Fab

1- assemble all ribs in DT9446 jig, weld as per dwg D2989 \(\text{D2}\)- tack weld mesh on basket as per dwg D2989 using DT9446 jig \(\text{M3}\)- to locate hinges and shims use D2989-041, weld as per dwg D2989 \(\text{A/R} \) ER316 S.S. Rod

Batch: MID 9213

110

QC

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

0.00

120

QC

QC6- Inspect dimensions to drawing

Memo

S orlappi

SM 09/04/20 /x

Quality Control

Work Order ID 50198

July 10, 2009 11:24:13 AM



Page 2

Item ID:

D2989-043

Accept

Accept

Qty

Setup Start

Stop



Revision ID: Item Name:

D

Basket Lid Assembly

Start Date: Required Date: 7/28/09

7/16/09

Start Qty: 1.00

Req'd Qty: 1.00

Cust Item ID: Customer:

Draw

Number

Reference:

Approvals:

QC:

Process Plan:

Date: _____ Tooling:

SPC (Y/N):

Date:

Date:

Draw

Rev.

Plan

Code

Run Start

Reject

Qty

Stop

Number Stamp

Insp.

Reject

Sequence ID/ **Work Center ID**

130



Powdercoat

Powder Coating

Operation Description

White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel

Date: ____

Set Up/ **Run Hours**

QC3- Inspect Part Finish

140



Quality Control

Memo

150

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

W 91.57.28

Page 1

Picklist Print

July 10, 2009 11:24:12 AM

Work Order ID: 50198

Parent Item: D2989-043RevD

Parent Item Name: Basket Lid Assembly

Comments:



Start Date: 7/16/09

Required Date: 7/28/09

Start Qty: 1.00

Required Qty: 1.00

	Comments:									start Qty. 1.00	•	Kequilea Qiy.	1.00
	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
167	D2989-17RevD D D D D D D D D D D D D D D D D D D		Manufactured	No			100	Each	0.0000	1.0000	348427	1 lx	SY 09/07/
	D2989-3RevD		Manufactured	No			100	Each	3.0000	1.0000			
					Warehou	<u>ise</u>	Loc (<u>Oty</u>	Loc Code				
					Loca	<u>tion</u>							
					Main Wa	rehouse							
					ST			3			i	011	04/20
						48328		1		_	<u>l</u> .	N 09.	07/20
						48506		2		. —	<u> </u>		•
	D2989-4RevD		Manufactured	No ,			100	Each	3.0000	1.0000			

Warehouse	Loc Qty	Loc Code		
Location				
Main Warehouse				
ST	3			
48329	1			
48503	2			

IX Sy 09/07/20

July 10, 2009 11:24:12 AM

Work Order ID: 50198

Parent Item:

D2989-043RevD

Parent Item Name:

Basket Lid Assembly

Comments:



Start Date: 7/16/09

Required Date: 7/28/09

Start Qty: 1.00

Required Qty: 1.00

Comments:								Start Qty: 1.00			Required Qty: 1.00	
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2989-5RevD		Manufactured	No			100	Each	8.0000	2.0000			
				<u>Warehou</u> <u>Loca</u> Main Wa	<u>tion</u>	<u>Loc</u>	<u>Oty</u>	Loc Code				
				ST			8				011	<i>i</i> 1
					48330		4		_	\Im_{X}	SM 09	107/20
D3182-1RevA			NI.		48505	100	4	12 0000			-	
Hinge		Manufactured	No			100	Each	12.0000	2.0000			
Timge				<u>Warehou</u> <u>Loca</u>		Loc	<u>Oty</u>	Loc Code				
				Main War	rehouse						_	
				ST			12			a _x	SHO91	1
					45504		3		_	dx	90 [لاكمر .	07120
D3442-3RevA		Manufactured	No		48453	100	9 Each	10.0000	2.0000	··	-	
Shim									-			
				<u>Warehou</u>	<u>se</u>	Loc	<u>Qty</u>	Loc Code				
				Loca	<u>tion</u>							
				Main War	ehouse							
				ST			10		_		- 4	
					42718		1		_	^	SH 09	107/20
					47265		2		_	₽X	N 1 09	JUTIAU

48504

July 10, 2009 11:24:12 AM

Work Order ID: 50198

D2989-043RevD Parent Item:

Parent Item Name: Basket Lid Assembly

Comments:



Start Date: 7/16/09

Required Date: 7/28/09

Start Oty: 1.00

Required Qty: 1.00

Comments:								ì	Start Qty: 1.00		Required Qty: 1.00	
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3827-041RevA Manufactured Rib Assembly (Inboard)		No			100	Each	6.0000	1.0000				
				<u>Wareho</u> <u>Loc</u> Main W	ation	Loc	<u>Oty</u>	Loc Code				
				ST	48454		6 6		<u></u>	Ιχ	SY 091	مداتن
D3832-5RevA		Manufactured	No			100	Each	4.0000	1.0000			
` ,				Wareho		Loc	<u>Otv</u>	Loc Code				
				<u>Loc</u> Main Wa	ation arehouse							
				ST	archouse		4				0.1	
					46307		1		_	IX	M091	(27/20
					48216		3					OFIAC
D3838-041RevA Rib Assembly (Basket Lid,		Manufactured	No			100	Each	3.0000	1.0000		- 	
				Wareho	use	Loc	<u>Oty</u>	Loc Code				
				Loc	<u>ation</u>							
				Main W	arehouse							
				ST			3		_		Ma	, ,
					48333 48502		1 2		_	/x	N 09.	107/20
					70302		2		_			

Picklist Print

July 10, 2009 11:24:12 AM

Page 4

Work Order ID: 50198

D2989-043RevD

Parent Item Name:

Basket Lid Assembly

Comments:

Parent Item:



Start Date: 7/16/09

Required Date: 7/28/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Bin **Primary** Item Location Last Location Route Seq ID

Unit of Measure

Qty on Hand

Remaining **Qty To Pick**

Qty Issued Date Issued

Status

D3838-042RevA

Manufactured

No

100

Each

3.0000

1.0000

Rib Assembly (Basket Lid, RH)

Warehouse Location Main Warehouse

ST

48334 48501 3

Loc Qty

Loc Code

(gty 2)

B44767









